


<b>Company</b>	AJ Networks	<b>Date of Inspection</b>	21/Apr/2021
----------------	-------------	---------------------------	-------------

Brand	Machine type:	Manufactured Year	Serial number	Hourmeter
Haulotte	Scissors	2015	CE807066	231

**Reported failure and/or work required by the customer:**

Inspection					
N°	Safety	Reference	OK	NOK	N/A
0.1	Campaign / OI	For Haulotte machine no pending OI / SB / NI			
0.2	Periodic inspection	Check Validity	v		
0.3	Periodic maintenance	Cable, chain changed according recommendation?	v		
N°	Chassis	Reference	OK	NOK	N/A
1.1	Wheels and Tyre	Installation OK / No damage on rim and tyre (Foam, slices)	v		
1.2	Drive Hub	Without leakage Oil	v		
1.3	Axle Extensible	Normal opening and closing of the mechanism			
1.4	Stabilizer cylinder Front-Rear	Properly installed / Without oil leakage			
1.5	Steer & Oscillating cylinder	Properly installed / Without oil leakage	v		
1.6	Hoses	Without cracks and oil leakage	v		
N°	Turntable	Reference	OK	NOK	N/A
2.1	Battery	Electrolyte level / Terminals / cable	v		
2.2	Ground control	Correct functionality (Joystick, Switch, E Stop, Lamp)	v		
2.3	Engine	Check oil level, not smoking, start properly, idles			
2.4	Hydraulic pump & manifold	Without oil leakage	v		
2.5	Hydraulic Tank	Appropriate level / Without oil leakage	v		
2.6	Hoses	Without cracks and oil leakage	v		

N°	Booms & scissor	Reference	OK	NOK	N/A
3.1	Hydraulic cylinders	Properly installed / Without oil leakage	v		
3.2	Power track	Operating free / links aligned			
3.3	Hoses / Electrical cables	Correctly positioned and tensioned, without damage	v		
3.4	Arms / Booms / Pins / Link part	Properly installed without structure damage	v		
N°	Platform	Reference	OK	NOK	N/A
4.1	Platform structure	Properly fixed / Swing gate latch / footswitch	v		
4.2	Upper control box	Correct functionality (Joystick, Switch, E Stop, Lamp)	v		

 For each NOK found, please indicate comments, and inform workshop manager.



### Notes / Comments

Person responsible for control:

Signature: Unseob Kim

Date of Inspection: 21/Apr/2021

N°	Add on for used equipment for Trade in		OK	NOK
5.1	CE certificate	Present		
5.2	Safety decals	Installed & Legible		
5.3	Painting & Corrosion	No excessive corrosion and structure safe		v
5.4	Tyre wear	Tyres have minimum 30% remaining tread.	v	
5.5	Battery status	Batteries hold charge for more than 24hrs	v	

5.6	General status	Ready to use	v	
5.7	Star ratings	<p>-Limited use or recently replaced. Free of visible wear or defect</p> <p>-Performs within the tolerances expected for age and type of model</p> <p>-Although performing, show indication of needing repair or replacement</p> <p>-Needs immediate repair or replacement to function as expected</p> <p> Please circle the relevant status.</p>		




**Notes / Comments**



Cleaning and painting should be done by AJ before shipping.




Person responsible for control:

Signature: Unseob Kim

Date of Inspection: 21/Apr/2021

CURRENT CONDITION	MANDATORY OR OPTIONAL TO CARRY OUT
<p><b>Machine data plate</b></p>	<p><b>Indicate whether mandatory or optional and manhours</b></p>
	<p>Provide part number of required parts, qty and pictures (if available from ESP)</p>
<p>SN.CE807066. 2015Y</p>	
<p><b>Battery condition</b></p>	
<p>Trojan. T145. 2018Y. Working condition</p>	
<p><b>Upper control box condition</b></p>	
 <p>Rental condition</p>	
<p><b>Platform condition</b></p>	
	

CURRENT CONDITION	MANDATORY OR OPTIONAL TO CARRY OUT
<p><b>Lower control box condition</b></p> 	
<p><b>Filter &amp; oil condition</b></p> <p>Rental condition</p>	
<p><b>Electrical Wiring &amp; Components condition</b></p>  <p>Rental condition</p>	
<p><b>Safety decals condition</b></p>	

CURRENT CONDITION	MANDATORY OR OPTIONAL TO CARRY OUT	
<p><b>Emergency System condition</b></p> 	<p>Rental condition</p>	
<p><b>Tires conditions</b></p> 	<p>Rental condition</p>	
<p><b>Lift cylinder conditions</b></p> 	<p>No leaks Rental condition</p>	
<p><b>Steering cylinder conditions</b></p> 	<p>No leaks Rental condition</p>	