


Company	AJ Networks	Date of Inspection	20/Apr/2021
----------------	-------------	---------------------------	-------------

Brand	Machine type:	Manufactured Year	Serial number	Hourmeter
Haulotte	Scissors	2015	CE806845	267

Reported failure and/or work required by the customer:

Inspection					
N°	Safety	Reference	OK	NOK	N/A
0.1	Campaign / OI	For Haulotte machine no pending OI / SB / NI			
0.2	Periodic inspection	Check Validity	v		
0.3	Periodic maintenance	Cable, chain changed according recommendation?	v		
N°	Chassis	Reference	OK	NOK	N/A
1.1	Wheels and Tyre	Installation OK / No damage on rim and tyre (Foam, slices)	v		
1.2	Drive Hub	Without leakage Oil	v		
1.3	Axle Extensible	Normal opening and closing of the mechanism			
1.4	Stabilizer cylinder Front-Rear	Properly installed / Without oil leakage			
1.5	Steer & Oscillating cylinder	Properly installed / Without oil leakage	v		
1.6	Hoses	Without cracks and oil leakage	v		
N°	Turntable	Reference	OK	NOK	N/A
2.1	Battery	Electrolyte level / Terminals / cable	v		
2.2	Ground control	Correct functionality (Joystick, Switch, E Stop, Lamp)	v		
2.3	Engine	Check oil level, not smoking, start properly, idles			
2.4	Hydraulic pump & manifold	Without oil leakage	v		
2.5	Hydraulic Tank	Appropriate level / Without oil leakage	v		
2.6	Hoses	Without cracks and oil leakage	v		

N°	Booms & scissor	Reference	OK	NOK	N/A
3.1	Hydraulic cylinders	Properly installed / Without oil leakage	v		
3.2	Power track	Operating free / links aligned			
3.3	Hoses / Electrical cables	Correctly positioned and tensioned, without damage	v		
3.4	Arms / Booms / Pins / Link part	Properly installed without structure damage	v		
N°	Platform	Reference	OK	NOK	N/A
4.1	Platform structure	Properly fixed / Swing gate latch / footswitch	v		
4.2	Upper control box	Correct functionality (Joystick, Switch, E Stop, Lamp)	v		

 For each NOK found, please indicate comments, and inform workshop manager.



Notes / Comments

Person responsible for control:

Signature: Unseob Kim

Date of Inspection: 20/Aprl/2021

N°	Add on for used equipment for Trade in		OK	NOK
5.1	CE certificate	Present		
5.2	Safety decals	Installed & Legible		
5.3	Painting & Corrosion	No excessive corrosion and structure safe		v
5.4	Tyre wear	Tyres have minimum 30% remaining tread.	v	
5.5	Battery status	Batteries hold charge for more than 24hrs	v	

5.6	General status	Ready to use	v	
5.7	Star ratings	<p>-Limited use or recently replaced. Free of visible wear or defect</p> <p>-Performs within the tolerances expected for age and type of model</p> <p>-Although performing, show indication of needing repair or replacement</p> <p>-Needs immediate repair or replacement to function as expected</p> <p> Please circle the relevant status.</p>		




Notes / Comments



Cleaning and painting should be done by AJ before shipping.


Person responsible for control:

Signature: Unseob Kim

Date of Inspection: 20/April/2021

CURRENT CONDITION	MANDATORY OR OPTIONAL TO CARRY OUT
<p>Machine data plate</p>  <p>SN.CE806845. 2015Y</p>	<p>Indicate whether mandatory or optional and manhours</p> <p>Provide part number of required parts, qty and pictures (if available from ESP)</p>
<p>Battery condition</p> <p>Madi in Korea. Rocket 6240-260AH.2018Y.</p> <p>Working condition</p>	
<p>Upper control box condition</p>  <p>Rental condition</p>	
<p>Platform condition</p> 	

CURRENT CONDITION	MANDATORY OR OPTIONAL TO CARRY OUT
<p>Lower control box condition</p> 	
<p>Filter & oil condition</p> <p>Rental condition</p>	
<p>Electrical Wiring & Components condition</p>  <p>Rental condition</p>	
<p>Safety decals condition</p>	

CURRENT CONDITION	MANDATORY OR OPTIONAL TO CARRY OUT	
<p>Emergency System condition</p> 	<p>Rental condition</p>	
<p>Tires conditions</p> 	<p>Rental condition</p>	
<p>Lift cylinder conditions</p> 	<p>No leaks Rental condition</p>	
<p>Steering cylinder conditions</p> 	<p>No leaks Rental condition</p>	