

车间机器检查

WORKSHOP MACHINE INSPECTION

Ref QUAL

旧机必要进行的检查（从客户处接收机器时）

Obligatory control of used machines (when machine is received from the customer).

品牌/Brand	机器型号 Machine type:	生产年份 Manufactured Year:	序列号 Serial number :	工作小时数 Hourmeter :
Haulotte	Optimum 8	2015	CB806388	595

机器现有的故障 和/或 客户要求的工作:

Reported failure and/or work required by the customer:

1 设备各功能正常
2 油漆结构件基本完好. 整体5成新

检查/Inspection					
N°	安全/Safety	参考/Reference	OK	NOK	N/A
0.1	升级 Campain / OI	如果是 Haulotte 机器, 是否有未执行的 OI/NI/SB For Haulotte machine no pending OI / SB / NI	✓		
0.2	定期检查 Periodic inspection	检查保养记录和保养周期 Check Validity		✓	
0.3	定期维护 Periodic maintenance	电缆, 链条等形变是否超出磨损极限 Cable, chain changed according recommendation?	✓		
N°	底盘/Chassi	参考/Reference	OK	NOK	N/A
1.1	车轮和轮胎 Wheels and Tyre	安装正常/轮胎和轮毂边缘无损坏(起泡, 切割) Installation OK / No damage on rim and tyre (Foam, slices)	✓		
1.2	驱动轮毂 Drive Hub	没有漏油 Without leakage Oil	✓		
1.3	延伸轴 Axle Extensible	延伸机构能正常开启和关闭 Normal opening and closing of the mechanism	✓		
1.4	前后稳定器油缸 Stabilizer cylinder Front-Rear	安装合理/没有漏油 Properly installed / Without oil leakage	✓		
1.5	转向和摆动油缸 Steer & Oscillating cylinder	安装合理/没有漏油 Properly installed / Without oil leakage	✓		
1.6	油管 Hoses	没有开裂和漏油 Without cracks and oil leakage		✓	有部分开裂
N°	回转/Turnable	Reference	OK	NOK	N/A
2.1	电池 Battery	电解液液位/接线柱/线束 Electrolyte level / Terminals / cable	✓		
2.2	地面控制 Ground control	控制功能正常(手柄/拨杆开关/急停开关/灯) Correct functionality (Joystick, Switch, E Stop, Lamp)	✓		
2.3	发动机 Engine	检查油位, 没有黑烟, 启动正常, 怠速转速 Check oil level, not smoking, start properly, idles			✓
2.4	液压泵和歧管 Hydraulique pump & manifold	没有漏油 Without oil leakage	✓		
2.5	液压油箱 Hydraulique Tank	液位正常/没有漏油 Appropriate level / Without oil leakage	✓		
2.6	油管 Hoses	没有开裂和漏油 Without cracks and oil leakage		✓	有部分老化

车间机器检查

WORKSHOP MACHINE INSPECTION

Ref QUAL

N°	大臂和剪叉臂/Booms & scissor	参考/Reference	OK	NOK	N/A
3.1	液压油缸 Hydraulic cylinders	安装合理/没有漏油 Properly installed / Without oil leakage	✓		
3.2	伸缩链 Power track	活动正常/链接整齐 Operating free / links aligned	✓		
3.3	油管/电缆 Hoses / Electrical cables	正确定位和拉紧, 无损伤 Correctly positioned and tensioned, without damage	✓		
3.4	第一节臂/大臂/销子/链接 Arms / Booms / Pins / Link part	安装正确, 结构没有损坏 Properly installed without structure damage			✓
N°	平台/Plateform	参考/Reference	OK	NOK	N/A
4.1	平台结构 Plateforme structure	正确安装/门闩/脚踏开关 Properly fixed / Swing gate latch / footswitch	✓		
4.2	上控箱 Upper control box	控制功能正常 (手柄/拨杆开关/急停开关/灯) Correct functionality (Joystick, Switch, E Stop, Lamp)		✓	快插类 可损坏

! 对于每一个发现的 NOK, 请指出意见并通知车间经理。 For each NOK found, please indicate comments and inform workshop manager.

备注/评论:

Notes / Comments

1 整机5项新
2 结构件, 油漆比较完整,
3 电池需要更换, 线路管路需要重新调整

评估负责人签字:

Person responsible for control:

Jason

评估日期:

Signature:

2021.10.29

Date of Inspection:

车间机器检查

WORKSHOP MACHINE INSPECTION

Ref QUAL

N°	以旧换新/Add on for used equipment traded in		OK	NOK
5.1	CE 证书 CE certificat	是否缺失 Present		✓
5.2	安全贴纸 Safety decals	是否缺失/可以分辨 Installed & Legible		✓
5.3	油漆/腐蚀 Painting & Corrosion	没有过度腐蚀或影响结构安全 No excessive corrosion and structure safe	✓	
5.4	轮胎磨损 Tyre wear	轮胎至少有 30%的剩余胎面 Tyres have minimum 30% remaining tread.	✓	
5.5	电瓶状态 Battery status	电池可充电超过 24 小时 Batteries hold charge for more than 24hrs		✓

5.6	一般状况 General status	Ready to use		
5.7	星级标准 Star ratings	-全新/未适用的设备 Equipment New/Unused	★ ★ ★ ★ ★	
		-使用次数少或最近进行过更换的设备。设备无可见磨损或缺陷 Limited use or recently replaced. Free of visible wear or defect	★ ★ ★ ★	
		-在使用时长和型号的预期容差范围内运行的设备 Performs within the tolerances expected for age and type of model	★ ★ ★ ✓	
		-虽然仍在使用，但已有需要维修或更换迹象的设备 Although performing, show indication of needing repair or replacement	★ ★	
		-需要立即维修或更换才能正常工作的设备 Needs immediate repair or replacement to function as expected	★	
		! 请圈出相关状态。 Please circle the relevant status.		

备注/评论

Notes / Comments

评估负责人签字:

Person responsible for control:

Jason

评估日期:

Signature:

2021.10.29

Date of Inspection: